



This metal piece was bent, which kept the stepper unit from advancing properly