

# Service Bulletin: SB 50

**DATE:** March 2, 1993

**GAME:** Whitewater

**SUBJECT:** Intermittent or weak action from ball popper assembly A-15769

**CAUSE:** Rubber Grommet missing or installed incorrectly on ball popper assembly

We have had a few customers reporting that the rubber grommet (part #23-6420) on the ball popper assembly of "Whitewater" pinballs have been missing. See the diagram below for the location of the grommet. Please check your game and install a new grommet if needed.

