REMOVE TOPPER
FROM CARTON

REMOVE 4 SCREWS AND
HOLE PLUG FROM TOP OF
BACKBOX

SAVE THESE FOR LATER

755-76645-00

STEP #3

- SET THE TOPPER ON YOUR BACKBOX.
- PUSH THE CABLES THROUGH THE ACCESS HOLE ON THE TOP OF THE CABINET.
- SECURE THE TOPPER TO THE BACKBOX WITH THE SCREWS YOU REMOVED IN STEP #2.
- STORE THE HOLE PLUG IN A SECURE PLACE IN CASE YOU REMOVE THE TOPPER.


755-7645-00

# STEP #4

TOPPER KIT WIRING HARNESS INSTALLATION

1. Unlock display panel, remove the back glass and remove plug for access hole.
2. Place the Topper on top of the back box, drop the cables from the topper through the hole located on the top center section of the back box.
3. Plug the RJ45 coming from the topper to CN12 of the CPU.
4. Plug the other end of the power cable to CN7 of the power distribution board.
5. Dress the wiring harness neatly with existing cable clamps.

#2

#4

#3

#5

TOPPER IS NOW INSTALLED