


# UPPER PLAYFIELD PARTS



**Miscellaneous**

- A-13204-50032
- A-13769-50032
- A-13769A-50032
- A-15646-3
- A-16120-1
- A-18159-1
- A-19603-8
- A-19603-9
- A-19603-10
- C-13940-1
- 03-9315-1
- 03-9315-2

- Bottom Arch Assembly
- Screened Playfield
- Screened Mini-playfield
- Opto SW-24 P.C.B. Assy.
- D.C. Motor Control Assembly
- 10 Opto P.C.B. Assembly
- Large Right Rear Plastic Assy.
- Small Rear Plastic Assy.
- Wood Rail Plastic Assy.
- 5 Sw & Diode P.C.B. Assy.
- \*\*Full Playfield Mylar
- Mini-playfield Mylar

- 03-9315-3
- 03-9315-4
- 03-9315-5
- 03-9315-6
- 20-6500

- Ball Return Mylar
- Ball Return Mylar
- Upper Loop Mylar
- Main Loop Mylar
- Steel Ball 1 1/6" (5)

†Located Under Mini-playfield

\*Not Shown

\*\*The Shadow hardcoat playfield does not require a full mylar. However, mylars can be purchased through your local Bally Distributor.